

Packing list for ATA3500

NO	Model	Description	Quantity	Unit
1	Nylon tube (red)	φ6*1 (20m)	1	Pc
2	Polyethylene pipe	φ11*8 (3m)	1	Pc
3	O-ring	φ6*1.9	6	Pc
4	O-ring	φ10*2	10	Pc
5	O-ring	φ14*2	6	Pc
6	O-ring	φ32*2.65	3	Pc
7	O-ring	φ40*2.65	3	Pc
8	Fuse	RF1-30 3A	3	Pc
9	Fuse	BGXP 0.5A 20M/M	4	Pc
10	Nut(small)	SPA8.940.831	4	Pc
11	Threaded bushing (large)	SPA8.215.065/12	8	Pc
12	Bush	SPA8.210.030	8	Pc
13	Sealed gasket	SPA8.370.206	8	Pc
14	Light correction board	SPA8.402.900	1	Pc
15	Connector of acetylene regulator	SPA8.470.056	1	Pc
16	Anti-explosion spring	SPA8.026.008	1	Pc
17	Wrench	8*10	1	Pc
18	Wrench	12*14	1	Pc
19	Wrench	17*19	1	Pc
20	Screwdriver (“+”)	75mm*4mm	1	Pc
21	Acetylene pressure reducing valve	YQE-213	1	Pc
22	Igniter		1	Pc
23	Cable	RS232 (1.5M)	1	Pc
24	Power cable	10A/250V	1	Pc
25	Hollow cathode lamp Cu	copper	1	Pc
26	Atomizer	AAS-HPSF	1	Pc
27	Atomizer tube		1	Pc
28	combustion head		1	Pc
29	Air dryer and filter assembly	QSL type 0.1-1Mpa	1	Pc
30	Holder of air dryer and filter assembly	SPA8.045.125	1	Pc
31	Dongle		1	Pc
32	User manual		1	Pc
33	Certificate		1	Pc
34	Warranty Card		1	Pc