



Title of Change:	Product Discontinuance Notice Niigata parts
Last Time Buy Date:	05 Jul 2021
Last Ship Date:	05 Jul 2022
Contact information:	Contact your local ON Semiconductor Sales Office

Description and Purpose:

The products contained in this notice are part of a product portfolio renewal process whereby ON Semiconductor is exiting unprofitable legacy products and shifting investments to our growth portfolio aligned to strategic markets.

The activity for the products on the attached device list has declined to a level that warrants the discontinuance of these products or the manufacturing facility has been announced for a closure. Some devices may have an alternate standard device or a suggested replacement as an alternative solution.

ON Semiconductor wishes to promptly inform our customer of our intent to exit this small portion of our overall portfolio so that you may plan appropriately and effectively for replacement devices.

ON Semiconductor has provided a list of replacement devices, where available, to aid in this process.

For those devices that have no recommended replacement identified, ON Semiconductor has partnered with Rochester Electronics who will carry any remaining device inventory to potentially allow for a continued source after ON Semiconductor has completed its business process

PLEASE NOTE: ON Semiconductor may implement minimum order quantities or dollar amounts based on inventories available. Also, Devices on this Product Discontinuance become NCNR (Non-Cancelable, Non-Returnable).

For questions or concerns regarding this notification, please contact your local sales office or customer service representative.

Additional contacts are:

Americas:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

USA

Europe:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

Slovakia

Japan:

Isao Usuki (isao.usuki@onsemi.com)

☎ + 81 3 6880 1771

Japan

Asia Pacific:

Stephen Ng (stephen.ng@onsemi.com)

☎+852 2689 0209

China

NOTE: UPON PUBLICATION OF THIS DISCONTINUANCE NOTICE, ON SEMICONDUCTOR ALLOWS THREE (3) MONTHS FROM THE NOTICE DATE TO PLACE FINAL LIFETIME PURCHASE ORDERS. ACCEPTANCE IS SUBJECT TO REASONABLE ORDER QUANTITIES, PRODUCT AVAILABILITY AND ALL OTHER APPLICABLE TERMS AND CONDITIONS

NOTE: TO ALLOW AN ORDERLY EXIT FROM THE MARKET, PRODUCT SHALL NOT BE DELIVERED AFTER FIFTEEN (15) MONTHS BEYOND THE ANNOUNCEMENT DATE.

List of Affected Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

To view attached Parts List:

1. Download pdf copy of the PCN to your computer
2. Open the downloaded pdf copy of the PCN
3. Click on the paper clip icon available on the menu provided in the left/bottom portion of the screen to reveal the Attachment field
4. Then click on the attached file/s

Japanese translation of the notification starts here.
通知の日本語訳はここから始まります。

Note: *The Japanese version is for reference only. In case of any differences between the English and Japanese version, the English version shall control.*

注：日本語版は参照用です。英語版と日本語版の違いがある場合は、英語版が優先されます。



製品廃止通知

文書番号: PD23900Z

発行日: 07 Apr 2021

変更件名:	新潟製品の製品廃止通知
最終購入日:	05 Jul 2021
最終出荷日:	05 Jul 2022
連絡先情報:	現地のオン・セミコンダクター営業所にお問い合わせください

説明および目的:

本通知に記載された製品は、製品ポートフォリオの更新プロセスの一環で、これにより、オン・セミコンダクターは、採算が取れないレガシー製品を終了し、戦略的市場に合わせた成長ポートフォリオへの投資に切り替えます。

添付の製品リストに記載の製品の状況は、それらの製品の廃止または製造施設の閉鎖が必要となるレベルまで減少しました。製品の一部には代替の標準製品または代替策としての推奨代替品がある場合があります。

オン・セミコンダクターはお客様が適切かつ効率的に製品を変更できるよう、弊社すべてのポートフォリオのごく一部を廃止する意向を速やかにお客様にご連絡したいと考えております。

オン・セミコンダクターはこのプロセス支援のため、入手可能な代替品のリストを提供しています。

オン・セミコンダクターは推奨代替品が見つからない製品については、ロチェスター・エレクトロニクスと提携し、オン・セミコンダクターが業務プロセスを完了した後も、残りの製品在庫を提供できる体制を取ります。

注意: オン・セミコンダクターは在庫数状況により最小発注数または金額を設定する場合があります。また、本製品廃止の製品は NCNR (解約不可、返品不可)となります。

この通知に関してご不明な点がございましたら、現地の営業所または顧客サービス窓口にお問い合わせください。

以下の連絡先もご利用いただけます:

米国:

Tom Siegel (tom.siegel@onsemi.com)

☎ +1 765 868 5022

アメリカ合衆国

欧州:

Andrej Tomasik (andrej.tomasik@onsemi.com)

☎ +421 33790 2229

スロバキア

日本:

Isao Usuki (isao.usuki@onsemi.com)

☎ +81 3 6880 1771

日本

アジア太平洋:

Stephen Ng (stephen.ng@onsemi.com)

☎ +852 2689 0209

中国

注: 本廃止通知により、オン・セミコンダクターは発行日より 3 ヶ月間最終購入注文を受け付けます。受注は適切な発注数、製品在庫数、および適用されるその他すべての取引条件に従うものとします

注: 市場より正常に廃止するため、製品は発行日から 15 ヶ月を超えた後は納入されないものとします。

影響を受ける標準部品の一覧:

注: 標準の部品番号 (既製品) のみが部品一覧に記載されます。本 PCN に影響を受けるカスタム 部品は、PCN メールの顧客の特定の PCN の付属文書、または PCN カスタマイズポータルに記載されています。

添付文書を見るには:

1. ご使用のコンピューターに PDF 版の PCN をダウンロードします。
2. ダウンロードした PDF 版の PCN を開きます。
3. 添付欄を見るには、画面左 / 下部分のメニュー上にあるクリップ アイコンをクリックしてください。
4. 添付ファイルをクリックします



Appendix A: Changed Products

PCN#: PD23900Z
Issue Date: Apr 08, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
NVMFS5A140PLZWFT3G			NVMFWS3D0P04M8LT1G	ON Semiconductor
NFCS1060L3TT			#NONE	#NA
STK534UC60A-E			NFAP1060L3TT	ON Semiconductor
STK534UC90A-E			#NONE	#NA
STK551U3A2A-E			#NONE	#NA
STK5C4U332J-E			NFAQ0560R43T	ON Semiconductor
LB1838JM-TRM-E			#NONE	#NA
LB11600JV-TLM-E			LV8907UWR2G/LV8961H	ON Semiconductor
NCP4060AMNTXG			FAN65004B	ON Semiconductor
NCP5339MNTXG			NCP303151AMNTWG	ON Semiconductor
NCP3231AMNTXG			NCP3230MNTXG and NCP3284MNTXG	ON Semiconductor
NCP3231MNTXG			NCP3230MNTXG and NCP3284MNTXG	ON Semiconductor
NCP3231BMNTXG			NCP3230MNTXG and NCP3284MNTXG	ON Semiconductor
FDG6301N-F085			#NONE	#NA
NVMFS6B14NT1G			FDWS86068-F085	ON Semiconductor
NVATS5A106PLZT4G			FDD9511L-F085	ON Semiconductor
NVATS5A113PLZT4G			NVD5117PLT4G-VF01	ON Semiconductor
NVATS5A112PLZT4G			NVD5117PLT4G-VF01	ON Semiconductor
NVC6S5A354PLZT1G			NVGS5120PT1G	ON Semiconductor
NVMFS5A140PLZT3G			NVMFS3D0P04M8LT1G	ON Semiconductor
NVMFS5A160PLZT1G			NVMFS5113PLT1G	ON Semiconductor
NVMFS5A140PLZWFT1G			NVMFWS3D0P04M8LT1G	ON Semiconductor
NVC3S5A51PLZT1G			NVR5124PLT1G	ON Semiconductor
NVMFS5A160PLZWFT1G			#NONE	#NA
LC89091JA-AH			#NONE	#NA
LC89091JA-H			#NONE	#NA
LE24512AQF-AH			CAT24C512HU5IGT3	ON Semiconductor
LC75700T-TLM-E			#NONE	#NA
LA72910V-TLM-H			#NONE	#NA
LA72912V-TLM-H			#NONE	#NA
LV8411GR-TE-L-E			#NONE	#NA
LV8417CS-TE-L-H			#NONE	#NA
LC79401KNE-E			#NONE	#NA
LC79430KNE-E			#NONE	#NA
LC717A00AJ-AH			AT42QT1060	Microchip
LC717A00AR-NH			AT42QT1060	Microchip
LC717A30UJ-AH			AT42QT2120	Microchip
LC717A10AJ-AH			AT42QT2160	Microchip
LB11620T-TLM-H			BD63001AMUV	ROHM
LB11696V-TLM-E			BD63001AMUV	ROHM
LV8827LFQA-NH			BD63006MUV	ROHM
LV8121V-TLM-H			BD63007MUV	ROHM



Appendix A: Changed Products

PCN#: PD23900Z
Issue Date: Apr 08, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
LV8804FV-TLM-H			BD63242EFV	ROHM
LV8805SV-TLM-H			BD63242EFV	ROHM
LB1930MC-AH			BD63576NUX	ROHM
LB1938FA-BH			BD63576NUX	ROHM
LV8402GP-TE-L-H			BD6381EFV	ROHM
LV8405V-TLM-E			BD6381EFV	ROHM
LV8806QA-MH			BD67173NUX	ROHM
LB1638MC-AH			BD6736FV	ROHM
LB11870-TRM-E			BD67929EFV	ROHM
LA6585TFA-BH			BD6981FVM	ROHM
LB1862MC-AH			BD6982FVM	ROHM
LB11961-TLM-H			BD6995FV/APX9211	ROHM/AMPEC
LV8498CT-TE-L-H			BU64244GWZ, BU64249GWX	ROHM
LC75829PW-H			BU91510	ROHM
LC75857W-E			BU97501	ROHM
LV8728MR-AH			DRV8424	TI
LV8729V-TLM-H			DRV8424	TI
LV8731V-TLM-H			DRV8825	TI
LV8732V-TLM-H			DRV8825	TI
LV8760T-TLM-E			DRV8829	TI
LV8741V-TLM-E			DRV8825	TI
LV8711T-TLM-H			DRV8848	TI
LV52511MNZTXG			TB62D787	Toshiba
LV88553JA-AH			STL6900A	SENTELIC
LV8702V-TLM-H			TB67S128FTG	TOSHIBA
LV88554JA-AH			STL6900A	SENTELIC
LB1838M-TLM-E			TC78H621FNG	TOSHIBA
LB1848MC-AH			TC78H621FNG	TOSHIBA
LB1838M-TRM-E			TC78H621FNG	TOSHIBA
LB1940T-TLM-H			TC78H621FNG	TOSHIBA
LB1936V-TLM-E			TC78H621FNG	TOSHIBA
LB1948MC-AH			TC78H621FNG	TOSHIBA
LV8549MC-AH			TC78H621FNG	TOSHIBA
LB1973JA-AH			TC78H621FNG	TOSHIBA
LB1836M-TLM-E			TC78H621FNG	TOSHIBA
LB1909MC-BH			TC78H621FNG	TOSHIBA
LV8548MC-AH			TC78H621FNG	TOSHIBA
LV8712T-TLM-H			TC78S600FNG	TOSHIBA
LC75760UJA-AH			TLC6C5712	TI
LB1205M-TLM-E			ULN2069B	STmicroelectronics
LV3327PV-TLM-H			#NONE	#NA
NVMFS6B85NLT1G			NVMFS040N10MCLT1G	ON Semiconductor



Appendix A: Changed Products

PCN#: PD23900Z
Issue Date: Apr 08, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
TCP-5068UB-DT			#NONE	#NA
LV8741VL-TLM-E			DRV8825	TI
TCP-5082UB-DT			#NONE	#NA
NGTB10N60FG			#NONE	#NA
NGTB10N60R2DT4G			#NONE	#NA
NGTB03N60R2DT4G			#NONE	#NA
TIG056BF-1E			#NONE	#NA
TIG058E8-TL-H			#NONE	#NA
NGTB15N60R2FG			#NONE	#NA
TIG065E8-TL-H			#NONE	#NA
NGTB40N65IHL2WG			FGHL40T65MQD	ON Semiconductor
TIG067SS-TL-2W			#NONE	#NA
NGTB35N60FL2WG			FGHL40T65MQD	ON Semiconductor
NGTB15N120IHRWG			NGTB15N120FL2WG	ON Semiconductor
NGTB20N120IHRWG			NGTB25N120FL3WG	ON Semiconductor
NGTB30N135IHRWG			#NONE	#NA
NGTB20N135IHRWG			#NONE	#NA
NGTB40N135IHRWG			#NONE	#NA
NGTB40N120S3WG			NGTB40N120FL3WG	ON Semiconductor
NGTB40N120IHRWG			NGTB40N120FL3WG	ON Semiconductor
NGTG40N120FL2WG			NGTB40N120FL3WG	ON Semiconductor
STK672-432BN-E			#NONE	#NA
STK672-430AN-E			#NONE	#NA
STK672-440AN-E			#NONE	#NA
STK672-442AN-E			#NONE	#NA
STK672-440BN-E			#NONE	#NA
STK672-442BN-E			#NONE	#NA
STK672-640AN-E			#NONE	#NA
STK672-630AN-E			#NONE	#NA
STK681-332-E			#NONE	#NA
STK681-360-E			#NONE	#NA
STK554U392C-E			NFAQ1560R43T	ON Semiconductor
STK551U362A-E			NFAP1060L3TT	ON Semiconductor
BSS138LT7G			BSS138LT1G	ON Semiconductor
STK57FU394AG-E			#NONE	#NA
NTB60N06T4G			FDB13AN06A0	ON Semiconductor
NTD2955-1G			FDD5614P	ON Semiconductor
NTMFS6B14NT1G			FDMS86183	ON Semiconductor
NTMFS6B05NT1G			FDMS86101	ON Semiconductor
NTMFS6B03NT1G			FDMS86181	ON Semiconductor
NTB45N06LT4G			FQB50N06LTM	ON Semiconductor
NTD3055L170T4G			FQD13N06L	ON Semiconductor



Appendix A: Changed Products

PCN#: PD23900Z
Issue Date: Apr 08, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
NTP2955G			FQP11P06	ON Semiconductor
NTB45N06T4G			HUF76429S3S	ON Semiconductor
NTD24N06T4G			NTD5C688NL	ON Semiconductor
NTB5605PT4G			NTB25P06	ON Semiconductor
NTD3055L104-1G			RFD3055LESM	ON Semiconductor
KSC2223YMTF			MMBT5089LT1G	ON Semiconductor
MMBT5962			MMBT5088LT1G	ON Semiconductor
2N6517CTA			PZTA96ST1G	ON Semiconductor
SFT1342-W			#NONE	#NA
BBS3002-DL-1E			#NONE	#NA
BBS3002-TL-1E			#NONE	#NA
SMP3003-TL-1E			#NONE	#NA
SMP3003-DL-1E			#NONE	#NA
WPH4003-1E			#NONE	#NA
2SK536-TB-E			#NONE	#NA
SMA3101-TL-E			#NONE	#NA
CPH5504-TL-E			#NONE	#NA
NDFPD1N150CG			#NONE	#NA
2SK3745LS-1E			#NONE	#NA
NDUL03N150CG			#NONE	#NA
NDTL03N150CG			#NONE	#NA
NDUL09N150CG			#NONE	#NA
2SK3746-1E			#NONE	#NA
2SK3747-1E			#NONE	#NA
NDFP03N150CG			#NONE	#NA
2SB1203S-E			2SA2039-E	ON Semiconductor
12A02CH-TL-E			12A02MH-TL-E	ON Semiconductor
2SA1419T-TD-H			2SA1419S-TD-E	ON Semiconductor
2SB1204T-E			2SA2039-E	ON Semiconductor
2SB1203S-TL-E			2SA2039-TL-E	ON Semiconductor
2SB1205T-E			2SA2039-E	ON Semiconductor
2SB1203T-TL-E			2SA2039-TL-E	ON Semiconductor
2SB1124T-TD-E			2SA2125-TD-E	ON Semiconductor
2SB1204T-TL-E			2SA2040-TL-E	ON Semiconductor
2SB1124S-TD-E			2SA2125-TD-E	ON Semiconductor
2SB1202T-TL-E			2SA2126-TL-E	ON Semiconductor
2SB1121S-TD-E			2SB1123S-TD-E	ON Semiconductor
2SB1122S-TD-E			2SB1123S-TD-E	ON Semiconductor
2SB1122T-TD-E			2SB1123T-TD-E	ON Semiconductor
2SB1216S-E			2SB1215S-E	ON Semiconductor
2SB1216S-TL-E			2SB1215S-TL-E	ON Semiconductor



Appendix A: Changed Products

PCN#: PD23900Z
Issue Date: Apr 08, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
2SC3649T-TD-H			2SC3649T-TD-E	ON Semiconductor
2SC6094-TD-E			2SC5964-TD-E	ON Semiconductor
SFT1202-E			2SC4027S-E	ON Semiconductor
SFT1202-TL-E			2SC4027T-TL-E	ON Semiconductor
2SC6096-TD-H			2SC6096-TD-E	ON Semiconductor
2SC4134S-TL-E			2SC4135S-TL-E	ON Semiconductor
PCP1203-TD-H			2SD1623T-TD-E	ON Semiconductor
15C02CH-TL-E			2SD1048-7-TB-E	ON Semiconductor
2SD1802S-TL-E			2SD1802T-TL-E	ON Semiconductor
2SK932-22-TB-E			2SK932-23-TB-E	ON Semiconductor
30C02CH-TL-E			50C02CH-TL-E	ON Semiconductor
50C02MH-TL-E			50C02CH-TL-E	ON Semiconductor
50A02SS-TL-E			50A02CH-TL-E	ON Semiconductor
1HN04CH-TL-W			BSS123K	Diodes Incorporated
50C02SS-TL-E			50C02CH-TL-E	ON Semiconductor
CPH5518-TL-E			CPH5520-TL-E	ON Semiconductor
CPH5518-TL-H			CPH5520-TL-E	ON Semiconductor
ECH8502-TL-H			CPH5524-TL-E	ON Semiconductor
ECH8501-TL-H			CPH5524-TL-E	ON Semiconductor
CPH3461-TL-W			DMN30H4D1L	Diodes Incorporated
ECH8102-TL-H			CPH6122-TL-E	ON Semiconductor
CPH3459-TL-W			DMN30H4D1L	Diodes Incorporated
CPH6444-TL-W			FDC5612	ON Semiconductor
CPH6354-TL-W			FDC5614P	ON Semiconductor
CPH6442-TL-W			FDC5661N-F085	ON Semiconductor
CPH6445-TL-W			FDC5661N-F085	ON Semiconductor
CPH6347-TL-W			FDC608PZ	ON Semiconductor
ATP405-TL-H			FDD3670	ON Semiconductor
CPH6443-TL-W			FDC653N	ON Semiconductor
ATP106-TL-H			FDD4685	ON Semiconductor
ATP108-TL-H			FDD4141	ON Semiconductor
SFT1342-TL-W			FDD5614P	ON Semiconductor
ATP102-TL-H			FDD6685	ON Semiconductor



Appendix A: Changed Products

PCN#: PD23900Z
Issue Date: Apr 08, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
CPH3448-TL-W			FDN537N	ON Semiconductor
CPH3351-TL-W			FDN5618P	ON Semiconductor
CPH3462-TL-W			FDN8601	ON Semiconductor
BBL4001-1E			FDPF041N06BL1-F154	ON Semiconductor
2SK3703-1E			FDPF320N06L, FDPF55N06	ON Semiconductor
2SJ652-1E			FQPF47P06	ON Semiconductor
NDDP010N25AZT4H			FQD9N25	ON Semiconductor
BFL4026-1E			FQPF6N90C	ON Semiconductor
CPH3215-TL-E			NSS40201LT1G	ON Semiconductor
MCH6101-TL-E			MCH6103-TL-E	ON Semiconductor
MCH6202-TL-E			MCH6203-TL-E	ON Semiconductor
CPH3105-TL-E			NSS60200LT1G	ON Semiconductor
MCH6545-TL-E			MCH6541-TL-E	ON Semiconductor
CPH3212-TL-E			NSS60201LT1G	ON Semiconductor
MCH3209-TL-E			NSS60201LT1G	ON Semiconductor
CPH3109-TL-E			NSS60200LT1G	ON Semiconductor
MCH3109-TL-E			NSS60200LT1G	ON Semiconductor
MCH6421-TL-E			NTJS3157N	ON Semiconductor
6HP04CH-TL-W			NTR5105PT1G	ON Semiconductor
MCH3376-TL-W			NTS4101P	ON Semiconductor
CPH3457-TL-W			NTR4170NT1G	ON Semiconductor
MCH3333A-TL-W			NTS4173P	ON Semiconductor
MCH3475-TL-E			NTS4173P	ON Semiconductor
MCH3478-TL-W			NTS4173P	ON Semiconductor
MCH3476-TL-H			NTS4173P	ON Semiconductor
ATP103-TL-H			#NONE	#NA
MCH3375-TL-W			NTS4173P	ON Semiconductor
ATP104-TL-H			#NONE	#NA
ATP112-TL-H			#NONE	#NA
ATP114-TL-H			#NONE	#NA
ATP302-TL-H			#NONE	#NA
ATP301-TL-H			#NONE	#NA
VEC2315-TL-W			QH8JC5	Rohm Semiconductor
VEC2415-TL-W			QH8K51	Rohm Semiconductor
VEC2616-TL-W			QS8M31	Rohm Semiconductor
PCP1403-TD-H			RJP020N06	Rohm Semiconductor



Appendix A: Changed Products

PCN#: PD23900Z
Issue Date: Apr 08, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
MCH3377-TL-W			SSM3J134TU	Toshiba Semiconductor
MCH3474-TL-W			SSM3K116TU	Toshiba Semiconductor
MCH3481-TL-W			SSM3K62TU	Toshiba Semiconductor
MCH3486-TL-W			SSM3K341TU	Toshiba Semiconductor
MCH3484-TL-W			SSM3K62TU	Toshiba Semiconductor
MCH6344-TL-H			SSM6J402TU	Toshiba Semiconductor
MCH6321-TL-E			SSM6J422TU	Toshiba Semiconductor
MCH6448-TL-H			SSM6K403TU	Toshiba Semiconductor
MCH6445-TL-W			SSM6K407TU	Toshiba Semiconductor
MCH6660-TL-W			SSM6L39TU	Toshiba Semiconductor
MCH6663-TL-W			SSM6L40TU	Toshiba Semiconductor
MCH6662-TL-W			SSM6N39TU	Toshiba Semiconductor
MCH6661-TL-W			SSM6N40TU	Toshiba Semiconductor
MCH6664-TL-W			SSM6P40TU	Toshiba Semiconductor
2SK3666-3-TB-E			TF412ST5G	ON Semiconductor
TF414T5G			TF412ST5G	ON Semiconductor
PCP1402-TD-H			ZVN4525Z	Diodes Incorporated
1HP04CH-TL-W			ZVP3310F	Diodes Incorporated
PCP1405-TD-H			ZVN4525Z	Diodes Incorporated
CPH3362-TL-W			ZXMP10A13F	Diodes Incorporated
LC706203CM			#NONE	#NA
LC709203FQH-01TWG			LC709204FXE-01TBG	ON Semiconductor
LC709203FXE-01MH			LC709204FXE-01TBG	ON Semiconductor
LC709203FQH-04TWG			LC709204FXE-01TBG	ON Semiconductor
LV88562RTXG			STL6900A	SETELIC
LV88552JA-AH			STL6900A	SETELIC
LV88552RTXG			STL6900A	SETELIC
LV88553RTXG			STL6900A	SETELIC
LV88554RTXG			STL6900A	SETELIC
LV88562JA-AH			STL6900A	SETELIC
LV88563RTXG			STL6900A	SETELIC
LV88564JA-AH			STL6900A	SETELIC
LV52204MUTBG			TPS61161	TI
LV88564RTXG			STL6900A	SETELIC
LV8716QA-MH			DRV8848	TI
STK682-010-E			#NONE	#NA
LC898214XD-MH			LC898249AXHTBG	ON Semiconductor
STK5Q4U352J-E			NFAQ0860L36T	ON Semiconductor
STK581U3C2D-E			NFAM3065L4B	ON Semiconductor

**Appendix A: Changed Products****PCN#: PD23900Z**
Issue Date: Apr 08, 2021

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
SVC230-TB-E			BB814	Infineon
2SA2039-H			2SA2039-E	ON Semiconductor
SVC272-TL-E			BB914	Infineon
2SB1204S-E			2SA2039-E	ON Semiconductor
SFT1443-TL-W			FQD13N10	ON Semiconductor
FW4604-TL-2W			FDS8958A	ON Semiconductor
SFT1345-TL-H			FQD8P10	ON Semiconductor
SFT1445-TL-H			FQD19N10	ON Semiconductor
FW217A-TL-2W			SH8K26	ROHM
MCH3383-TL-H			SSM3J133TU	Toshiba Semiconductor